

27th St Automotive

1105 N 27th St
Boise, ID 83702



208-890-8739
27thstauto.com

27th St. Automotive Inspection

Customer:	Jose Prado	License:	1A 8G494
Vehicle:	2008 Chevrolet Tahoe	VIN:	
Inspection date:	7/1/2016	Odometer:	in: 172,031- miles
Repair Order #:	9242	Technician:	Hector Prado

We have inspected your vehicle with the following results:



Hector Prado, Technician



Joaquin Cordero, Service Advisor

Inspected in Good Condition

Brake System Inspection	Observation	Action
Front Brake Pads	LF 5 mm RF 5 mm	
Front Brake Rotors	LF Spec. ___ RF Spec. ___ LF Act. ___ RF Act. ___	
Brake Fluid Condition	< 100 ppm 100 ppm	Brakes - Brake Fluid Service DOT3


Inspected in Good Condition

Brake System Inspection		
✓ 4 Corner Photos	✓ Front Brake Hoses	✓ Front Brake Caliper
✓ Front Wheel Bearing	✓ Front ABS Sensor/Wiring	✓ Front Lug Studs/Nuts
✓ Rear Brake Hose	✓ Rear ABS Sensor/Wiring	✓ Rear Lug Studs/Nuts
✓ Master Cylinder	✓ Brake Lights	

Immediate Action Required (Safety)

Brake System Inspection	Observation	Action
Rear Brake Calipers	Not Applicable <i>Image(s):</i> Rear Brake Calipers1.jpg Rear Brake Calipers2.jpg <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	Remove and replace brake calipers, pads & rotors

Additional Information



Rear Brake Calipers



Rear Brake Calipers